6
HITCH AND HYDRAULICS

HIDRAULICS						
REPLACES	RH Leveling Box and Parts (1939-64)	REPLACES	Left Hand Leveling Rod			
	(1939-64)	<b>9N564B</b> \$70.34	Rod and fork assembly, hydraulic lift, LH. For tractors 9N, 2N, 8N, NAA (1939-1954).			
NCA577A	Right hand leveling box assembly. For all Ford	<b>C5NNB863C</b> \$68.40	Leveling rod and yoke, LH. For tractors 5000, 7000 (1965-1975); 5600, 5700, 6600, 6700, 7600, 7700 (1975-1981); 5610, 5900, 6610, 6710, 7610, 7710, 7910 (1981-).			
\$62.95	tractors (1939-1964); except 501 & Majors. Also for 2000, 3000 (1965-1975).	E4NNN673AA	6710, 7610, 7710, 7910 (1981-). Rod and yoke, LH. For tractors 3055, 3550, 4000			
<mark>9N595</mark> \$1.81	Pin. For all tractors 1939-1964 (except Majors); for 2000, 3000, 4000 (1965 & up); 3600, 4600 (1975 & up).	\$38.55	(except 4110) (1965-1975); 3600, 3600N, 4600SU (1975-1981); all purpose with Cat. I on 3910, 4110, 4610 (1981-); 4610SU (1981-1982). Replaces C5NNN673A.			
<b>957E566</b> \$5.52	Knuckle, RH leveling assembly. For all tractors 1939-1964 (except Majors); for 2000, 3000, 4000 (1965 & up); 3600, 4600 (1975 & up).	<b>C7NN564B</b> \$48.62	Leveling rod assembly, LH, adjustment is 21-3/4" to 24-3/4". For tractors 2000, 3100, 3120, 3300, 3310, 3400, 3500, 4110 w/dual category linkage (1965-1/1970); 334 L/cab (1981-4/1983);			
NCA579B \$14.82	Shaft and gear, length 14"; thread length 4".		3610 L/cab (1981-1982).			
9N554 \$17.39	Bearing assembly.	EONNB484DA \$70.52	Leveling rod assembly, LH, adjustment from 27-1/2" to 32". For tractors 3000, 4000			
9N594 \$4.25 B9NN568A	Lever handle.		(1965-1975); 2600, 3600, 4600, 231, 233, 333 (1975-1981); 2310, 2610, 3610, 4610, 230A, 334,			
\$8.19	Gear, leveling box pinion.		335, 530A, (1981-1991).			
REPLACES	RH Box Assembly (1965 to 1983)	<b>C5NNB863CWKF</b> \$106.04	Leveling rod assembly, LH, adjustment is 27" to 33". For tractors 5000, 7000 (1965-1975); 5600, 5700, 6600, 6700, 7600, 7700 (1975-1981); 5610, 6610, 6710, 7610, 7710 (1981-1991).			
<b>E0NN569AA</b> \$67.99	Box assembly, leveling RH. For tractors 2000, 3100, 3120, 3300, 3310, 3400, 3500, 4110 with dual category linkage (1965-1/1970); 334 less	REPLACES	Leveling Box Parts			
	cab (1981-4/1983); 3610 less cab (1981-1982).					
<b>C5NN569AM</b> \$84.00	Box assembly, leveling RH, adjustment from 27-1/2" to 32". For tractors 3000, 4000, (1965-1975); 2600, 3600, 4600, 231, 233, 333 (1975-1981); 2310, 2610, 3610, 4610, 230A, 334, 335, 530A (1981-1991).	<mark>9N585A</mark> \$25.01	Fork, hydraulic lift leveling rod, RH. Length 10-1/4". For tractors 9N, 2N, 8N, NAA (1939-1954).			
D2NNN983AWF \$179.66	Box assembly, leveling RH, adjustment is 26" to 32". For tractors 5000, 7000 (1965-1975); 5600, 5700, 6600, 6700, 7600, 7700 (1975-1981);	NCA585B \$39.98	Fork, hydraulic lift leveling rod, RH. Length 14-3/4". For tractors 600, 800 (1955 & up); row crop HiClear (1957 & up).			
	5610, 6610, 6710, 7610, 7710 (1981-1991).	E0NN585BA \$35.85	Fork, hydraulic lift leveling rod, RH. Length 14" center hole to end 3/4" threads. For tractors			
REPLACES	Universal Economy Leveling Assembly		2000, 3000 (use with dual category linkage, 62" fork slot) (1965-1/1970); 3600 (1975-1981); 2310,			
			2610, 2810, 2910, 3610, Industrials 230A, 234, 334, 335, 530A, 62" fork slot (1981-). Can replace C5NN585D.			
<b>LB152</b> \$19.65	Universal Economy Leveling Assembly. 1-5/16" body of high strength tubing, thread size, 7/8" fine thread-study clevis at each end with 5/8" pin holes. May be used right or left.	<b>C5NN585B</b> \$52.34	Fork for leveling box. Length 20". For tractors 3055, 3550 series, 4000 (except 4110), 4140, 4200 (1965-1975).			





E0NN585CA \$70.14 C5NN579F \$11.90	Fork for leveling box. Length 20" thread 13/16"-12. For tractors 3900, 4100, 4600 (1975-1981); Cat. II on 4110, 4610 (1981-2/1990); industrials: 420, 515, 532, 535 (1975-1981). Replaces D3NN585A. Shaft with pinion gear. Length 12".fOR TRACTORS 2000 (EXCEPT 2300); 3100, 3120, 3310, 3400, 3500, 4110 (1965 & up); 3600, 4600		Lift Arm Repair End
<b>C5NN579E</b> \$11.90	(1975 & up). Shaft with pinion gear. Lrngth 12". for tractors 4000 (1965 & up), 4600 with cab (1975 & up).	<b>LAS192</b> \$8.45	Lift arm repair end, bent, forged. Category I, 7/8" pin hole, 1-3/4" width at weld end. 5-1/4" overall length.
<b>E2NN579AA</b> \$33.71	Shaft with pinion gear. Length 14-5/8", thread 13/16"-12. For tractors 3900, 4100, 4600 (1975-1981); Cat. II, 4110, 4610 (1981-2/1990); Industrials 420, 515, 532, 535 (1975-1981).	<b>LAS292</b> \$13.13	Lift arm repair end, bent, forged. Category II, 1-1/8" pin hole, 1-3/4" width at weld end. 5-1/2" overall length.
REPLACES	Forged Lower Lift Arm	REPLACES	Lower Link Reducing Sleeves
	Assemblies	EC0NG992AA \$1.25	Sleeve bushing. Reduces 1-1/8" lift arm ball socket to accomodate 7/8" draw pin. 1-3/4" long.
<mark>9N555B</mark> \$51.23	Hydraulic lift arm. Heavy duty w/forged ball joint ends. Length 32". Painted Blue. For tractors 9N,	<b>P2004</b> \$0.81	Sleeve bushing. Reduces C5NN557B, ball to accomodate Cat. 1-7/8" draw pin. 1-3/8" long.
ψ01.20	2N, 8N, NĀA, right or left.	REPLACES	Lift Arm Balls and Retainer
<b>JSA1002R</b> \$56.13	Lower lift arm heavy-duty with forged ball-joint ends. Category 1 accommodates 7/8" drawbar or lower link pins. Painted red. Length 32". Replacement for Ford 9N555B right or left.	DDN995233 \$4.37 C5NN557A	Springs for 1965-75 & Up Ball, lower link, 1-3/8" wide. Category I. Ball, lower link, 1-3/4" wide. Category II.
<b>D0NN555DRH</b> \$69.15	Lower lift arm, RH, 5160 steel. 32" hole centers. For tractors 600, 800 (1955-1964); 2000, 3000, 2600, 3600 (1965-1981).	\$4.22 <b>C5NN557B</b> \$4.50	Ball, 1-3/8" wide. Category II.
D0NN555CLH \$69.15	Lower lift arm, LH, 5160 steel. 32" hole centers.	<b>C5NNN557B</b> \$2.60	Spring, ball retainer. For dual-category lift arms.
REPLACES	Lower Link Support Pin		
NCA563C \$18.15	Lower link support pin. For tractors 8N, NAA, 600, 601, 800, 801, 1801, 2000, 4000, (1948 to 1964); row crop hi clearance: 700, 701, 900, 901, (1955 to 1964); 2000, 3000, 4000 without differential lock, (1965 to 1975); 3600, 4600, (1975 to 1981).		





REPLACES

**Lower Link Pins** 



Replaces		Category	Pin Dia.	Useable Leng	th Overall Leng	th Thread Dia.	Adjustable Jam Nut	Fixed Shoulder
P70220	\$2.79	0	5/8"	1-1/8"	3-7/8"	5/8"	Summut	onounder
P7221	\$4.65	I-0	7/8"	1-3/4"	4-1/2"	5/8"	Y	
251380	\$2.22	I	7/8"	1-3/4"	5-1/2"	7/8"		
251381F	\$3.09	1	7/8"	2-1/2"	6-7/16"	7/8"		
251546F	\$2.49	I	7/8"	1-3/4"	5-1/2"	7/8"		
251547	\$3.09	1	7/8"	2"	6-3/16"	7/8"		
P7212	\$5.75		1-1/8"	2"	6-5/16"	1-1/8"		Y
P2005	\$5.34	II	1-1/8"	1-3/4"	6-1/4"	1-1/8"	Y	
251382	\$4.25	ll to l	1-1/8"	1-3/4"	5-1/4"	7/8"		
P6501	\$3.09	Τ	7/8"	2-1/2"	6-1/2"	7/8"		
251383	\$4.56	II to I	1-1/8"	2-1/4"	6-1/2"	7/8"		
REPLACES	N	/liscellar	neous Pi	ns	JSA1200B	Top link, 16" body , cor		
					\$29.97	tractor & Category I in 19-1/2" to 29-1/2" over		
			1		<b>JSA2000B</b> \$33.75	Top link, 16" body, 1". ( Adjusts 21" to 33" over		
EC0E9 \$4.10 REPLACES	5" H		earth excavat 05.	3-3/4" usable length, ors E9, E10, E20, op Links	TL162 \$29.72	Top link, 16" body, 1". ( Forged ends with 1-1/ steel center section. A Dichromate plated. Comparable to our JS, except body & ends an	8" NC threads. Adjusts 21" to 3 A2000B & JSA.	Swedge 1" overall. 2000R
<b>JSA1012C</b> \$24.84	To	op link, 12" bo actor & Categ	ody, combina gory I implen	tion Category II nent ends. Adjusts	JSA2024B	colors. Top link, 24" body, 1".		joints.
	10	6" to 24" over	all. Dichroma	te plated.	\$25.76	Adjusts 29" to 41". Pai	nted blue.	
<b>JSA1000B</b> \$27.00	Tc Ad	op link, 16" bo djusts 20-1/2'	ody, 3/4". Cato " to 29" overa	egory I ball joints. III. Painted blue.	<b>JSA2020B</b> \$35.37	Top link, 20" body, 1". Adjusts 25" to 37". Pai		joints.
<b>JSA1020B</b> \$29.03		op link, 20" bo djusts 25" to		egory I ball joints. Painted blue.	REPLACES	Economy Forg	jed Top Li	nk
<b>JSA1024B</b> \$30.63		op link, 24" bo djusts 29" to		egory I ball joints. ainted blue.	<b>JSA5050</b> \$24.68	Top link 16" body. Cate Adjust 20-1/2" to 29" o center body. Replaces	verall. Dichrom	
<b>JSA1012-12</b> \$30.80	tra		gory I implen	tion Category II nent ends. Adjusts te plated.	<b>JSA1111</b> \$7.95	Top link end, 1-1/8" rig I, 3/4" pin hole.	ht hand thread,	Category
\$30.80								





			HYDRAULICS
<b>JSA1112</b> \$7.95	Top link end, 1-1/8" left hand thread, Category I, 3/4" pin hole.	<b>TL10813LP</b> \$25.76	Top link end, 1-3/8" thread, left hand, 1-1/4" hole.
REPLACES	Heavy Duty Top Links	<b>JSA2222</b> \$9.96	Top link end, 1-1/8" left hand thread. Category II, 1" pin hole.
	and a second sec	REPLACES	Weld-on Ball Sockets
<b>EC0N576AA</b> \$41.04	Category II heavy duty toplink. 1-1/4" NC thread. Forged ends with 1" sockets. 16" body, , adjusts from 23" to 32" overall. Dichromate plated.		
REPLACES	Top Links & Repair Ends	1	
<b>D0NN576B</b> \$89.82	Top link, combination Cat. I & II, adjusts 24-1/2" to 34-1/2".		
<b>D0NN576A</b> \$89.82	Top Link, Cat. II both ends, adjusts 24-3/4" to 34-3/4".	<b>B2226</b> \$5.55	Weld-on ball joint, 5/8" bore. Category 0.
DONNA911A \$27.36	Cat. II RH threaded repair end.	<b>BJ5418</b> \$6.47	Weld-on ball joint, 3/4" bore. Category I.
<b>D0NNA914B</b> \$29.51	Cat. II LH threaded repair end.	<b>BJ5211</b> \$7.71	Weld-on ball joint, 1" bore. Category II.
\$29.51 D0NNA914A \$33.92	Cat. I LH threaded repair end.	<b>B2229</b> \$10.31	Weld-on ball joint, 1-1/4" bore. Category III.
\$0.92 \$0.96	Reducer bushing, Cat. II to Cat. I, 1-15/16" long, 1" O.D., 3/4" I.D.	REPLACES	Top Link Reducer Bushings
REPLACES	Heavy Duty Ratchet Top Link		Contraction of the second seco
<b>TL175</b> \$100.83	Ratchet top link, 16" body. 1" Category II ball joints. Forged ends with 1-1/4" NC threads. Swedged steel center section. Adjusts 25-3/4" to 32-1/4" overall. Dichromate plated.	C7NNG993A \$1.71	Reducer bushing, converts ball socket in top (center) link. From Cat. II to Cat. I.
REPLACES	Threaded Repair Ends	Ŧ	
<b>JSA1111</b> \$7.95	Top link end, 1-1/8" right hand thread, Category	<b>B80209</b> \$0.81	Reducer bushing, 3/4" O.D. x 5/8" I.D. x 1-5/8" long. From Cat. I to Cat. 0.
<b>RE1717L</b> \$27.03	I, 3/4" pin hole. Top link end, 1-1/4" left hand thread. Category II, 1" pin hole.	<b>B833</b> \$1.13	Reducer bushing, 2" overall length, 1-1/4" O.D., 1" I.D. From Cat. III to Cat. II.
<b>RE1718R</b> \$30.77	Top link end, 1-1/4" right hand thread, category II, I" pin hole.		
JSA1112			
\$7.95	Top link end, 1-1/8" left hand thread, Category I, 3/4" pin hole.		
\$7.95 <b>TL10812RP</b> \$25.76			
TL10812RP	I, 3/4" pin hole. Top link end, 1-3/8" thread, right hand, 1-1/4"		



F-6-209



REPLACES	Forged Weld-on Repair Ends	REPLACES	Stabilizer Kits & Parts
		F2040-LH Call for Price	Left hand stabilizer kit. Stabilizer arm assembly w/bracket and U-bolts. For tractors 2910, 3910, 4110, 4610.
		<mark>SK-IND</mark> \$131.78	Stabilizer kit. Contains 4 mounting brackets w/pins and 2-JSA5050 top links. Fits most 3-point hitches on light industrial models.
<b>TLS310F</b> \$5.21	Top link weld-on repair end. Plain finish, forged, 3/4" hole, Category I.	F3040LH Call for Price	unit ussering wibidekets and
<b>TLS311F</b> \$8.94	Top link weld-on repair end. Plain finish, forged, 1" hole, Category II.	231253	U-bolts. For tractors 5610, 6610, 7610, 7710, 8210.
REPLACES	Combination Ball Sockets	\$42.08	Complete kit, red. For tractors 9N, 2N, 8N, NAA, 600, 800.
		F3040RH Call for Price	Right hand stabilizer kit, stabilizer arm assembly w/brackets and U-bolts. For tractors 5610, 6610, 7610, 8210.
		<b>230042R</b> \$10.31	Arm only, red. Length 31-1/2". For tractors 9N, 2N, 8N, NAA, 600, 800.
<b>B2310</b> \$8.76	Weld-on combination ball joint. For 5/8" or 3/4" pins. Category 0 or I.	F2040-RH Call for Price	Right hand stabilizer kit. Stabilizer arm assembly w/bracket and U-bolts. For tractors 2910, 3910,
<b>SBJ1</b> \$6.95	Weld-on combination ball joint. For 3/4" or 1" pins. Category I or II.	231254R	4110, 4610. Universal bracket, right or left
REPLACES	Top Link Pins	\$10.50	hand, red. Mounting bracket hole centers 5".
957E560	Upper link pin. Pin, 3/4" dia., 3" usable length. Fits all models using Cat. I link with 3/4" hole.	D9NNB856BB Call for Price	Stabilizer arm assembly less brackets and U-bolts. For tractors 2910, 3910, 4110, 4610.
\$1.16 <b>E381T9</b>	Supercedes 9N560. Pin, 3/4" dia. By 5" usable length. (Shoulder to	F3040-LB Call for Price	Stabilizer outer tube & inner bar assembly, no brackets or U-bolts. Replaces Tisco stabilizer
\$2.19 <b>E201GF9</b>	pin hole center). Top link pin, 1" dia. 5-5/8" eff. length. Cat. II.		assemblies F3040LH or F3040RH.
\$3.56 C5NN560A \$2.46	Upper link pin. For Major, 4000 (1965 & up).	<b>231253B</b> \$46.50	Complete kit, blue. For tractors 9N, 2N, 8N, NAA, 600, 800.
<b>E27N995272</b> \$2.46	Upper link pin. Fits Major diesel (4-15/16") (1952-1964).	F-LH Call for Price	Bracket, left hand stabilizer. For tractors 2910, 3910, 4110, 4610.
<b>P70706</b> \$1.16	Top link pin. Category O, 5/8" pin dia., 3" useable length. 4-1/2" overall length. Cat. 0.		62-magimmet.2

FORD



			HYDRAULICS
<b>230042B</b> \$11.64	Arm only, blue. For tractors 9N, 2N, 8N, NAA, 600, 800.		Stabilizer Links
<b>F-RH</b> \$30.00	Bracket, right hand stabilizer. For tractors 2910, 3910, 4110, 4610.		
F-UBOLT Call for Price	U-bolts. 2 required. For tractors 2910, 3910, 4110, 4610.	<b>C5NN454B</b> \$27.15	Link, stabilizer, RH. Cat. I & II. For tractors 3000 (except 3550) (1965-1975); 2600, 3600 (1975-1981); 4100, 4600SU (rigid - 1975-1981); 2610, 3610 (1981-); 4110, 4610SU (rigid - 1981-).
<b>231254B</b> \$10.50	Universal bracket, right or left hand, blue. Mounting bracket hole centers 5".		2010, 3010 (17819), 4110, 401030 (ligid - 17019).
231253XHD \$56.63	Complete Kit: Extra heavy duty, using stabilizers, arms of alloy spring steel. For tractors 9N, 2N, 8N, NAA, 600, 800. Red.		Link, stabilizer, LH. Cat. I & II. For tractors 3000
<b>230042XHD</b> \$19.29	Arm only, made of alloy spring steel, for kit 231253XHD, red only. 7/8" hole dia.	<b>C5NNN455B</b> \$27.15	(except 3550) (1965-1975); 2600, 3600 (1975-1981); 4100, 4600SU (rigid - 1975-1981); 2610, 3610 (1981-); 4110 4610SU (rigid - 1981-).
<b>SK23-6X</b> \$62.97	Lift stabilizer kit. For universal Cat.I, tractors 2000, 3000, 4000 (1965 & up): 2600, 3600 (1975 & up); not for dual-category equipment.	C5NN454C	
<b>SKA6251</b> \$22.97	Left hand arm only for SK23-6X. 7/8" hole dia.	\$24.15	Link, stabilizer, RH. Cat. I only. For tractors 2000, 4110 (1965-1975); 3000 (except 3550) (11/1970-1975); 2600, 3600 (1975-1981).
<b>SKA6252</b> \$24.15	Right hand arm only for SK23-6X. 7/8" hole dia.		$\sim$
REPLACES	Stabilizer Pins		
C5NNN873A \$5.24 251406F	Stabilizer pin	<b>C5NNN455C</b> \$24.15	Link, stabilizer, LH. Cat. I only. For tractors 2000, 4110 (1965-1975); 3000 (except 3550) (11/1970-1975); 2600, 3600 (1975-1981).
\$1.16	Stabilizer pin	REPLACES	Stabilizer Chains
<b>230044-WNL</b> \$1.16	Stabilizer pin	1121 211020	Stabilizer Chains
<b>251385</b> \$2.06	Stabilizer pin	DCK1	Drawbar check chain kit. Contains 1 (pair)
<b>141185-WNL</b> \$2.06	Stabilizer pin	\$24.92	anchors, 2 eyelets, 2 chains, 4 clevis with pins and hardware.
		CFPND936B-LB \$41.93	Single chain assembly; does not include brackets or U-bolt. For tractors 5000, 7000 (1965-1975); 5600, 6600, 6700, 7600, 7700 (1975-1981); 5610, 6610, 6710, 7610, 7710 (1981-).
		<b>CBPN598A</b> \$5.30	Check chain & pin kit. Contains chain, two clevis with pins & cotters. For all tractors 1939-1964 (except Majors & 501).

	Rep	lacement parts	to fit
6		FORD	
HITCH AND HYDRAULICS			
<b>APN582A</b> \$1.29	Clevis with pin and cotter key.	REPLACES	Economy Drawbars
REPLACES	Eyelet Assemblies		-
<b>NCB660A</b> \$4.19	Eyelet assembly. For tractors 9N, 2N, 8N, NAA, 700, 900.	<mark>9N5182A</mark> \$40.56	Standard red drawbar - 1" x 2-1/2" x 26", with 7/8" pins, (Category I).
<b>CEK3</b> \$5.22	Eyelet kit, includes eyelet assembly, nut & lock washer.	<b>9N5182B</b> \$40.56	Standard blue drawbar - 1" x 2-1/2" x 26", with 7/8" pins, (Category I).
	00	REPLACES	Drawbar Stay Arms
	Eyelet check chain, RH.	9N5374 \$8.76	Upper arm, std: red. All models.
NCA667A \$5.19		9N5375 \$8.91	Lower arm, std: red. All models.
		<b>9N5374B</b> \$9.15	Upper arm, std: blue. All models.
NCA678A	Eyelet check chain, LH.	<b>9N5375B</b> \$9.15	Lower arm, std: blue. All models.
\$7.44	6	REPLACES	Swinging Drawbar Assembly
REPLACES			1
REPLACES	Drawbar Anchor & Safety Chain		
05755007	Anchor, Drawbar link check chain (pair). For		and the
<b>957E5967</b> \$11.07	tractors 9N, 2N, 8N (1939-1952); NAA (1953-1954); 600, 700, 800, 900 (1955-1957); Dexta, Super Dexta (1958-1964); 2000, 4000	<b>SDA6</b> \$96.92	Swinging drawbar assembly. Complete kit. For 8N, NAA, 600 series.
	(1962-1964); 2000, 3000, 4000 (1965-1975); 2600, 3600, 4600 (1975-1981); 2610, 3610, 4610 (1981-2/1991). Replaces NCA597B.	<b>SDA8</b> \$108.36	Swinging drawbar assembly. Complete kit. For tractors 800 series except 820, 821.
9N5370	Chain, fixed drawbar safety chain assembly.	CONN805F \$30.14	Swinging drawbar. For SDA6, SDA8.
\$75.39	EXACT of ORIGINAL. For tractors; 9N, 2N, 8N, NAA (1939-1954).	NCA803B \$31.29	Clevis assy. w/pins. For SDA6, SDA8.
REPLACES	· · ·	NCA809A \$47.88	Drawbar hanger. For SDA6 kit.
REPLACES	Standard Heat Treated Drawbars	<b>NDA809A</b> \$59.99	Drawbar hanger. For SDA8 kit.
	-	<b>PT3</b> \$4.61	Pin for clevis assembly.
ONECODUT	Heat treated red standard drawbar. 30-1/2"	REPLACES	Swinging Drawbars
<b>9N5182HT</b> \$50.09	L hole center to hole center, 2-1/2" W, 1-1/8" thick.		
<b>9N5182HTB</b> \$35.43	Heat treated blue standard drawbar. 30-1/2" L hole center to hole center, 2-1/2" W, 1" thick.	<b>C5NN805C</b> \$151.25	Swinging drawbar, 32-7/8" O.L. with 1-1/2" offset. For tractors 2000, 3000 (except 3550) (1965-1975); 2600, 3600, 4100, 4600, 5600,
<b>DKN5182</b> \$50.40	Extra H.D. Heat treated drawbar, 1-1/2" x 3" x 26", with Cat. II pins. (1-1/8"). For Major diesel		6600, 7600, 7700 (1975-1981); 2610, 2810, 2910, 3610, 3910, 4110, 4610, 230A, 530A (1981-2/1990): 3230, 3430, 3930, 4130, 4630

Arthur's Tractors ~ <u>www.ArthursTractors.com</u> • 877-254-FORD (3673) • Fax: 724-349-3633 WE ARE NOT RESPONSIBLE FOR MIS-PRINTS OR PRICE CHANGES

(1981-2/1990); 3230, 3430, 3930, 4130, 4630

(3/1990-); 4830, 5030 (7/1990-).

diesel.





			IIIDIAOLICS
<b>C5NN805A</b> \$134.61	Swinging drawbar 37-1/2" O.L. For tractors 5000, 7000 (1965-1975).	<b>251542F</b> \$6.24	7/8" x 6-1/4" hitch pin.
		P1125 \$8.27	1-1/8" x 6-1/4" hitch pin.
		<b>P1250</b> \$10.92	1-1/4" x 6-1/4" hitch pin.
<b>C5NN805J</b> \$131.09	Swinging drawbar, 32-3/8" O.L. 540 rpm PTO. For tractors 2100, 3100 (1965-1975); 3900, 4100, 4600, 515, 532 (1975-1981); 2810, 2910, 3910, 4110, 4610 (1981-2/1990); 3230, 3430, 3930, 4130, 4630 (3/1990-); 4830, 5030 (7/1990-).	REPLACES	Snap-Lock Spring Hitch Pins
REPLACES	Drawbar Clevis Pin & Spring	EC0ND819JA \$5.40	3/4" dia. x 6-1/4" useable length.
<b>CBPN804A</b> \$8.00	Kit, pin & spring clip. For tractors 2000, 3000, 4000 (1965 & up). Also services earlier models (1953-1964) using swinging drawbar.	REPLACES	Agricultural Implement Linch Pins
<b>C5NN807D</b> \$2.94	Pin, swinging drawbar clevis.		
<b>311920</b> \$1.08	Spring clip.	DKLP91	Linch pin, 7/16" dia. pin x 1-3/4" useable length,
REPLACES	TISCO Hitch Pins with Hair Pin	\$0.20	1-5/8" dia. ring.
	Lock	DKP1/4 \$0.32	Linch pin, 1/4" O.D. pin x 1-1/4" long.
	C and	DKP3/16 \$0.23	Linch pin, 3/16 O.D. pin x 1-1/4 long.
		DKP-SD-1 \$0.65	Special Duty Linch Pin, 7/16 x 11/32.2 long, ring I.D. 1-5/8. Requires twice the force to open.
	<i>X</i>	DKPWCH	Linch pin with ring & chain, 7/16"
<b>251537</b> \$2.43	5/8" X 4-1/2" hitch pin.	\$0.75	pin diameter, 1-5/8" long, 1-11/16" ring diameter. DKP pin with safety chain.
<b>P6255</b> \$3.74	5/8" x 5-3/8" hitch pin.		
<b>251538</b> \$2.93	5/8" x 6-1/4" hitch pin.	DKP-SL-1 \$1.46	Linch pin with safety lock ring,
<b>251539</b> \$2.52	3/4 x 4-1/4 hitch pin.	<b></b>	7/16" dia. pin x 1-7/8" long, 1-11/16" ring dia.
<b>P7505</b> \$4 53	3/4" x 5-1/4" hitch pin.		2
\$4.53 <b>251540</b>	3/4" x 5-1/4" hitch pin. 3/4 x 6-1/4 hitch pin.		
\$4.53 251540 \$4.14 P8754			
\$4.53 <b>251540</b> \$4.14	3/4 x 6-1/4 hitch pin.		
\$4.53 <b>251540</b> \$4.14 <b>P8754</b> \$4.29 <b>251541</b>	3/4 x 6-1/4 hitch pin. 7/8" x 4-1/4" hitch pin.		

HITCH AN HYDRAULI				Replacemen FO				
REPLACES	Hair Pins			251412		2 diameter wire	e, 2-15/16 long	
	10			\$0 <b>251411</b> F	<b>).14</b>	diameter wire,	2-9/16 long.	
	10	2		HP6	3/3	2 diameter wire	e, 1-5/8 long.	
		9		\$0.2 HP7 \$0.2	0.10	2" dia., wire, 1-3	3/16" long.	
HP1	Hair Pin			\$0.2 HP8 \$0.2	La	r Pin		
\$0.83 HP2	Hair Pin			ψ0	150	-piece assortm		
\$0.83 <b>251413</b>	3/16 diameter w	vire 3-3/4 long			effe	ective impulse s	sales is include	ed.
\$0.32		r-Backhoe I						
		<b>P</b>						
Replaces	PUMP	CAPACITY GPM @ RPM	DIA	ТҮРЕ	ROTATION	MOUNTING	G INLET	OUTLET
	APPLICATION 701, 702, 703		<b>DIA</b> 3/4"	Round with	ROTATION Left hand	MOUNTING	G INLET	OUTLET 3/4" NPT
192504 \$407.40 195453	APPLICATION 701, 702, 703 loaders 701, 702, late 703	GPM @ RPM		Round with key Round with				
192504 \$407.40 195453 \$407.40 7702425-29Z \$453.11	APPLICATION 701, 702, 703 loaders 701, 702, late 703 loader 730 & 735 loaders	GPM @ RPM 14 @2000 14 @2000 21.5 @ 2000	3/4" 3/4" 7/8"	Round with key Round with key 13 spline	Left hand Left hand Left hand	Combo Combo 2 bolt SAE "B"	1" NPT 1" NPT 1-5/8"-12 ORB	3/4" NPT
195453 \$407.40 7702425-29Z	APPLICATION 701, 702, 703 loaders 701, 702, late 703 loader 730 & 735 loaders Hydraulic	GPM @ RPM 14 @2000 14 @2000 21.5 @ 2000 Pumps for Applicatio , gear type, d. For tractors 335, 531, 2600, 1); 234, 2310, 1-3/1983); 5610, 0, 7710	3/4" 3/4" 7/8"	Round with key Round with key 13 spline Donn60 \$630	Left hand Left hand Left hand OG Hyd D.00 mo trac trar (19 OKB Hyd 27.55 mo trac 770	Combo Combo 2 bolt SAE	1" NPT 1" NPT 1-5/8"-12 ORB ear type, housing. For ual power 0, 7000 ear type, housing. For 0, 6700, 7600,	3/4" NPT 3/4" NPT 1-5/16"-12





Hydraulic Pump, 16 gpm. For tractors 8000, 8700, 9000, 9700 (1968-1978).	CKPN600A \$66.02	Major repair kit. <b>For tractors:</b> 2000, 3000, 4000 (except independent PTO) (1965 & up); 2600, 3600, 4600 (1975 & up); also LCG, utility & industrial models. Services engine mounted pumps C5NN600AA, C7NN600Y, C5KNN600AB, & C7NN600Z (1965 & up); D4NN600C & D6NN600A (1975 & up).
and 2 adapters. For various loaders mounted on Ford tractors. For complete specifications see pump number 192504 on pump chart. Replaces	REPLACES	Hydraulic Piston Type Pump Parts
Pump less bracket, includes 2	NCA966E \$56.85	Shaft. For 4-cyl tractors (1953-1964) using NAA600D or NCA600F pump assemblies.
	<b>C3NN908A</b> \$25.34	Main gear for piston pump. For tractors NAA, 600, 700, 800, 900, 2000, 4000 series (thru 1964).
	D5NN1201A	Cone. For NCA966E shaft. (LM67048).
for 9N, 2N, 8N	\$4.61 <b>D5NN1202A</b> \$1.89	Cup, outer bearing. For NCA966E shaft. (LM67010).
pump repair kit. Contains cam blocks, pistons, chamber kits, PTO shaft bushing, safety valve, and gaskets.	NCA881A \$7.37	Needle bearing assy. pump hsg. For all tractors (1953-1964); except Majors.
Repair kit for hydraulic pump chamber.	C5NN966A \$68.66	Shaft. For tractors 2000, 3000, 4000 exc. Ind. PTO (1965 & up); 2600, 3600, 4600 (1975 & up).
Cam block, for hydraulic pump.	C0DW4621A	Bearing cone. For C5NN966A shaft. (M86649)
Piston, for hydraulic pump.	C0DW4616A	Bearing cup. For C5NN966A shaft. (M86610)
Bushing for hydraulic pump base, for PTO shaft.	169024	Bearing assembly, needle. For C5NN966A shaft.
Hydraulic Piston Type Pump Repair Kits	<b>22258X</b> \$2.55	Ball bearing, double shielded, I.D. 0.9843", O.D. 2.0472", W. 0.5906". For pump shaft DINN966A. For tractor 4500 with Vickers Vane-type pump.
	REPLACES	Pump Shaft Oil Seal
Repair kit. Services 1953 thru 1964 four cylinder gas or diesel tractors with piston type pump. For tractors NAA, 501, 600, 601, 700, 701, 800, 801, 900, 901, 2000, 4000. Will service either NCA600C or NCA 600E pump. Replaces	C5NN851A \$2.86	Hydraulic pump shaft oil seal. I.D. 0.9350", O.D. 2.004", W. 0.5315". For tractors NAA, 600, 700, 800, 900, 2000, 4000 series (1953-1964). Can replace NCA851A, D8NN851AA.
CCPN600A & CCPN600B.	REPLACES	Hydraulic Pump Gaskets &
Minor repair kit for 4.3 gpm piston type pump. For tractors 2000, 4110 (1965 & up); except independent PTO. Services C5NN600-AB.		Kits
Minor repair kit for 5.6 gpm piston type pump. For tractors 3000, 4000 (except 4110) (1965 & up); except independent PTO. services C5NN600-AA.	<b>FPN910B</b> \$5.72	Piston type hydraulic pump gasket & O ring kit. For all tractors 1953 & up.
	tractors 8000, 8700, 9000, 9700 (1968-1978). Pump assembly, 14 GPM. Includes pump, foot/flange bracket, 2 mounting bolts & washers, and 2 adapters. For various loaders mounted on Ford tractors. For complete specifications see pump number 192504 on pump chart. Replaces 3660. Pump less bracket, includes 2 adapters. <b>Hydraulic Pump Repair Parts</b> for 9N, 2N, 8N pump repair kit. Contains cam blocks, pistons, chamber kits, PTO shaft bushing, safety valve, and gaskets. Repair kit for hydraulic pump chamber. Cam block, for hydraulic pump. Piston, for hydraulic pump. Bushing for hydraulic pump base, for PTO shaft. <b>Hydraulic Piston Type Pump</b> <b>Repair Kits</b> <b>Sequence 10</b> Repair kit. Services 1953 thru 1964 four cylinder gas or diesel tractors with piston type pump. For tractors NAA, 501, 600, 601, 700, 701, 800, 801, 900, 901, 2000, 4000. Will service either NCA600C or NCA 600F pump. Replaces CCPN600A & CCPN600B. Minor repair kit for 5.6 gpm piston type pump. For tractors 3000, 4000 (except 4110) (1965 & up); except independent PTO. services	tractors 8000, 8700, 9000, 9700SecondPump assembly, 14 GPM. Includes pump, foot/flange bracket, 2 mounting bolts & washers, and 2 adapters. For various loaders mounted on Ford tractors. For complete specifications see adapters.REPLACESPump less bracket, includes 2 adapters.NCA966E \$56.85Pump less bracket, includes 2 adapters.NCA966E \$56.85Pump less bracket, includes 2 adapters.DSNN1201A \$4.61 DSNN1201A \$4.61 DSNN1202A \$1.89Hydraulic Pump Repair Parts for 9N, 2N, 8NNCA881A \$7.37pump repair kit. Contains cam blocks, pistons, chamber kits, PTO shaft bushing, safety valve, and gaskets.NCA881A \$7.37Repair kit for hydraulic pump chamber.CSNN966A \$66.66Cam block, for hydraulic pump.Sec.66 \$9.60Piston, for hydraulic pump.Sec.85 \$2.55Pupair KitsSec.85 \$2.55Repair kit. Services 1953 thru 1964 four cylinder gas or diesel tractors with piston type pump. For tractors NAA, 501, 600, 601, 700, 701, 800, 801, 90, 901, 2000, 4000. Will service either NCA600C or NCA 600F pump. Replaces CCPN600A & CCPN600B.Minor repair kit for 4.3 gpm piston type pump. For tractors 2000, 4100 (1965 & up): except independent PTO. Services 5NN600-AB.Minor repair kit for 5.6 gpm piston type pump. For tractors 3000, 4000 (except 4110) (1965 & up): except independent PTO. servicesMinor repair kit for 5.6 gpm piston type pump. For tractors 2000, 4100 (except 4110) (1965 & up): except independent PTO. servicesMinor repair kit for 5.6 gpm piston type pump. For tractors 2000, 4000 (except 4110) (1965 & up): except independent PTO. servi

Arthur's Tractors ~ <u>www.ArthursTractors.com</u> • 877-254-FORD (3673) • Fax: 724-349-3633 WE ARE NOT RESPONSIBLE FOR MIS-PRINTS OR PRICE CHANGES

6
HITCH AND HYDRAULICS

# FORD

<mark>9N611</mark> \$1.64	Gasket, hydraulic pump base to center housing. For tractors 9N, 2N, 8N (1939-1942).		(B) Pump Drive Couplings
<b>9N613</b> \$1.46	Gasket, valve chamber to base. For tractors 9N, 2N, 8N (1939-1942).	54C1067	<b>Chain Type</b> Coupling half, #40 chain sprocket, 16 tooth. Bor 1" dia., 6 spline. Used on Sherman 54B & 54C
NAA867A \$1.04	Gasket, piston pump cover, outer. For tractor NAA.	\$64.04 REPLACES	loader pump drive.
<b>D6NN867A</b> \$4.29	Gasket, piston pump cover, outer. For all tractors 1955 & up.		(B) Pump Drive Couplers
<b>C0NN869A</b> \$2.00	Gasket, piston pump cover, inner. For all tractors 1953 & up (except 620, 820).		
EAF911B \$0.74	Gasket, piston pump, gear housing to engine. For all tractors 1953 & up.		
NAA17382A \$0.26	Gasket, proofmeter drive bushing. For piston pumps (1953 & up); vane pumps (1955).	<b>L601-14</b> \$52.50	Coupler Complete, Morflex Series 302. Contain center member, 2 drive flanges with set screws
CAPN503B \$1.00	Lift cover o-ring kit. NAA models after S/N 20900.		and 4 bolts with lock nuts. Center member. (A) 3-1/8" dia.; (B) four 1/4"
CKPN485A \$2.82	Lift cover o-ring kit. For 600, 700 800, 900, 2000, 4000 series.	<mark>191061</mark> \$14.15	holes, 1-15/16" spacing. Drive flange; 3/4 round bore with set screw 1/4 x 3/8" #SSH4-6.
REPLACES	Hydraulic Pump Control and Safety Valves	<b>L36-4</b> \$67.31	Drive flange; 5/8" round bore with set screw 1/4" x 3/8" #SSH4-6.
<mark>9N640</mark> \$27.63	Hydraulic pump control valve. For tractors 9N, 2N.	<b>L36-5</b> \$67.31	Drive flange; 7/8" round bore with set screw 1/4 x 3/8" #SSH4-6.
8N638	Valve assy. For tractors 9N, 2N,	<b>L601-9</b> \$68.55	Morflex Series 352 coupler complete with 2 drive flanges, set screws, 4 bolts & lock nuts.
\$29.93	8N.	<b>192169</b> \$38.75	Center member. (A) 3-5/8" dia.; (B) four 5/16" holes, 2-1/4" spacing.
NAA638E \$60.93	Valve assy. For tractors NAA (1953-1954).	<b>192199</b> \$13.61	Drive flange; 3/4" round bore with set screw 1/4 x 3/8" SSH4-6.
NCA638C \$62.55	Valve assy. For tractors 600, 700, 800, 900, 2000, 4000	<b>L36-6</b> \$71.79	Drive flange; 5/8" round bore with set screw 1/4 x 3/8" #SSH4-6.
C7NN638E	(1955-1964). Relief valve, for hydraulic pump.	<b>L36-8</b> \$71.79	Drive flange; 7/8" round bore with set screw 1/4 x 3/8" #SS4-6.
\$84.86	For piston or gear type in center housing. For tractors 2000, 3000, 4000, 5000, 7000 (1965-1975).	<b>L36-19</b> \$71.19	Drive flange; 1" round bore with set screw 1/4' x 3/8" #SS4-6.
	4000, 3000, 7000 (1903-1973).	<b>L78-13</b> \$31.98	Drive flange, 13 spline for 7/8" dia. shaft. 5/16" dia. bolt holes 2-1/4" on center.

### p Drive Couplings pe

# Arthur's Tractors ~ www.ArthursTractors.com • 877-254-FORD (3673) • Fax: 724-349-3633 WE ARE NOT RESPONSIBLE FOR MIS-PRINTS OR PRICE CHANGES





REPLACES


(C) Hydraulic Pump Shafts



### **SEE NEXT PAGE FOR PRICES**

Replaces	APPLICATION	SHAFT	SHAFT	END A TYPE	END A SIZE	END B TYPE	END B
		DIAMETER	OVERALL				SIZE
			LENGTH				
197118	720 Loader	3/4"	8-3/8"	Key	3/4"	10 Spline	1"
195454	1953-64 Ford except	3/4"	9-3/8"	Key	3/4"	10 Spline	1"
	1808 & 4140						
194355	NAA, 600, 800	3/4"	9-1/4"	Key	3/4"	6 Spline	3/4"
194354	9N, 2N, 8N	3/4"	13"	Key	3/4"	6 Spline	3/4"
190760	9N, 2N, 8N	3/4"	13-1/16"	Key	3/4"	LH Thread	5/8"
292222	730 Loader	7/8"	10-3/8"	13 Spline	7/8"	13 Spline	7/8"
7701044	730 Loader	7/8"	11-5/8"	13 Spline	7/8"	13 Spline	7/8"
291951	730 Loader	7/8"	13-5/8"	13 Spline	7/8"	13 Spline	7/8"
7707570				-			
290481	730, 735 Loader	3/4"	8-7/8"			10 Spline	1"
C5NNA932C	535, 450 Ind. Tractors	NA	11-5/8"	4 bolt hub	13 Spline	7/8"	
E0NNA932AB	Ford Industrials Tractors	N/A	7-1/4"	4 bolt hub	13 spline	7/8"	
	445, 445A, 545, 545A				-		
REPLACES	Hydraulic Pump	Hubs &	Sheaves				

Hydraulic Pump Hubs & Sheaves



### SEE NEXT PAGE FOR PRICES

Replaces	APPLICATION	CENTER BORE	hub 0/a Dia	MOUNT HOLES QTY. & DIA.	MOUNT HOLES: TYPE	Hole Spacing	relief Dia	relief Depth	RELATED PARTS
191196	9N, 2N 8N	5/8" LH thread	3"	no holes 4 pins 11/32"	smooth	2-13/32"			190760 shaft
192161	9N, 2N 8N	3/4"-6 spline	3-3/8"	4, 1/4"	smooth	2-3/8"	1-1/4"	7/16"	192160 sheave, 194354 shaft
54C2055	Sherman 54 Series Loader	3/4"-6 spline	3-7/8"	4, 7/16"	smooth	2-3/4"	1-1/2"	7/16"	194354 shaft, or 194355 shaft
291061	730 Loader	7/8"-13 spline	4"	4, 7/16"	smooth	2-3/4"	1-1/2"	7/16"	291951, 292222, 7701044 shafts
C5NNN879A	730 Loader	7/8"-13 spline	5-1/4"	4, 7/16"	smooth	3-7/8"	1-9/16"	3/4"	291951, 292222, 7701044 shafts
291315	730 Loader	7/8"-13 spline	5-1/4"	4, 7/16"	threaded	3-7/8"	1-9/16"	7/16"	291951, 292222, 7701044 shafts
290421	1953-64 Ford except 1808 & 4140	1"-10 spline	4"	4, 7/16"	smooth	2-3/4"	1-3/8"	9/16"	195454 shaft

### F-6-216-A

### HYDRAULIC PUMP SHAFTS

407449	¢20.22
197118	\$38.33
195454	\$39.89
194355	\$25.05
194354	\$27.77
190760	\$14.12
292222	\$26.70
7701044	\$39.99
291951	\$22.34
7707570	\$53.81
290481	\$81.36
C5NNA932C	\$209.69
E0NNA932AB	\$160.50

### **HYDRAULIC PUMP HUBS & SHEAVES**

\$35.34
\$41.97
\$34.61
\$51.00
\$50.40
\$54.60
\$51.00



REPLACES	Quadrant Stop Kit	NAA530B \$21.69	Piston o-ring type. For tractor NAA (1953-1954). Optional for
<b>QSK3FF</b> \$6.18	Improved unit. Quadrant stop kit, includes wing nut 350890S36 and flat washer. Replaces 9N521. Fits all models (1939-1964); except Majors.		9N, 2N, 8N when used with o-ring NAA533A & NAA473A.
REPLACES	-	NAA533A \$0.79	O-ring for hydraulic lift piston. For tractor NAA.
REPLACES	Hydraulic Lift Cover Repair Kit	ψ0.75	
<b>LCRK928</b> \$9.52	Lift cover repair gasket kit. For tractors 9N, 2N, 8N.	<b>NAA473A</b> \$1.94	Back-up washer for lift piston NAA530B.
<b>LCRK53/54</b> \$6.57	Hydraulic lift cover repair kit. For tractors NAA (1953 to 1964).	<b>NCA473A</b> \$1.99	Back-up washer for piston NCA560B. For tractor 2000, 3000 (except 3550) (1955-1964); 4114 (1965 & up).
LCRK55/64	Hydraulic lift cover repair kit. For	<b>NCA533A</b> \$0.94	O-ring, 87111S95, for hydraulic lift piston NCA530B. (1955-1964).
\$8.39	1955 to 1964 tractor models: 501, 600, 601, 700, 701, 800, 801, 900, 901, 2000, 4000.	<mark>9N531C</mark> \$15.39	Rocker shaft bushing, 2 used. I.D. 2.000", O.D. 2-3/8", L. 3.00". For all tractors (1939-1964); 2000,
LCRK65UP \$10.75	Kit. For tractors 2000, 3000, 4000 (1965 & up).		3000 (except 3550), 4110 (1965-11/1971).
	Master repair kit, for hydraulic lift	<b>C5NN486F</b> \$3.24	Pin, hydraulic lift yoke. O.D. 1.00", usable length 4-3/8". For tractor Major 4000 (1965 & up).
<b>LCRK57</b> \$23.69	cover. For tractors 5000, 7000 (1965-1975).	<mark>9N550</mark> \$5.43	Special lock washer, hydraulic lift shaft to arm. For tractors; 9N, 8N, NAA (1939-1954).
<b>C5NNA967B</b> \$11.07	Gasket, hydraulic lift cover. For tractors 5000, 7000 (1965-1975).	<mark>9N529</mark> \$2.70	Felt, hydraulic lift draft control spring seat. For tractors: 9N, 2N, 8N, NAA, 600, 601, 700, 701, 800, 801, 900, 901, (1939-1962).
REPLACES	Parts for Ford Hydraulic Lift	8N486B	Pin, hydraulic lift yoke. For tractors; 8N, NAA,
9N510D	Hydraulic lift cylinder. For tractors 9N, 2N, 8N.	\$10.71	Jubilee, (1950-1954).
\$114.78	9IN, ZIN, 8IN.	<b>2N624</b> \$7.37	Seat, hydraulic lift draft control spring. EXACT of ORIGINAL. For tractors: All (1939 to 1964). Seat, hydraulic support lift draft control spring. <b>EXACT of ORGINAL</b> . For tractors; 9N, 2N, 8N,
9N530B \$23.84	Piston, hydraulic lift. For tractors 9N, 2N, 8N. Optional with NAA530B when used with o-rinh		NAA, Jubilee, 501, 600, 700, 800, 900, 2000, 4000, (1939 to 1964).
	NAA533A & washer NAA473A.	<b>352625S8</b> \$4.71	Hydraulic lift rocker pin to rear end housing. (3/4 x 3.14). EXACT of ORIGINAL. For tractors: 9N, 2N (1939 to 1947).
<mark>9N675</mark> \$8.07	Rings, steel, kit of three. For piston 9N530B.		
	$\bigcirc$		





REPLACES	Hydraulic Lift Parts	REPLACES	Hydraulic Lift Cover & Pump Repair Kit
	()	<b>B5001</b> \$8.69	O-ring kit for lift cover & pump. For tractors 2000, 3000, 4000, 5000, 7000 (1965-1975).
		REPLACES	Hydraulic Lift Housing Cover Gaskets
<b>87111S95</b> \$0.77	O-ring hydraulic lift piston. For tractors 2000, 3000 (1965-1975); 2600, 3600 (1975-1981); 2610, 3610 (1981-). Replaces NCA533A.		1000
<b>NCA473A</b> \$1.99	Back-up washer for piston NCA560B. For tractor 2000, 3000 (except 3550) (1955-1964); 4114 (1965 & up).		
<b>C5NN533A</b> \$0.45	O-ring, for lift cylinder piston. For tractors 4000 (1965-1975).	9N502 \$2.00 NAA502A	Hydraulic lift housing. For tractors 9N, 2N, 8N. Hydraulic lift housing cover. For tractors NAA.
<b>D1NN473A</b> \$4.68	Ring, back-up, for lift cylinder piston. For tractors 4000 (1965-1975). Replaces C5NN473A.	\$2.30 NCA502A \$1.74	Hydraulic lift housing cover. For tractors 1955-1964 (except Majors).
<b>373408S</b> \$0.77	O-ring, for lift cylinder piston. For tractors 5000, 7000 (1965-1974). For 3.75" diameter piston in tractors 5600, 5700, 6600, 6700, 7600, 7700	<b>C5NN502A</b> \$2.51	Hydraulic lift cover. For tractors 2000, 3000, 4000 (1965 & up).
	(1975-1981).	<b>C5NN518B</b> \$1.30	Disc, lift lever friction. For tractors (1939 & up).
REPLACES	Lift Cover O Ring Kits	<b>2N516B</b> \$20.28	Friction plate for hydraulic lift lever control. Use with disc C5NN518B. For tractors 1939 to 1964. Replaces 2N516A, 2N516A2.
	00	<mark>9N523B</mark> \$0.87	Lower link support plate. For tractors 9N, 2N.
	$\tilde{\circ}$	<b>9N552</b> \$0.27	Cylinder to center housing cover. For tractors 9N, 2N, 8N.
CADNEROD	Lift cover o-ring kit. NAA models after S/N	NAA552A \$0.32	Cylinder to center housing cover. For tractors NAA (1953-1954).
CAPN503B \$1.00	20900.	<b>9N553</b> \$0.54	Hydaulic lift cylinder housing. For tractors 9N, 2N, 8N.
CKPN485A \$2.82	Lift cover o-ring kit. For 600, 700 800, 900, 2000, 4000 series.	NAA553B \$0.83	Hydraulic lift cylinder housing, R.H. For tractors NAA.
REPLACES	Safety Valve for Lift Cylinder	REPLACES	Attachment Cylinder for
			Wagner
	1 10		
DDN984 \$27.63	Safety valve. For hydraulic lift cylinder on tractors Fordson Major (11/1960-1964); 4000 (except	<b>WAG8-51</b> \$263.55	Economy double acting attachment cylinder. Replaces H800-51. 2-1/2" bore, 17-3/4" stroke, 26-12" closed, 3/4" clevis pin.
	4110); 5000, 7000 (1965-1979).	1C4759 Call for Price	Kit: seals & o-rings.

Arthur's Tractors ~ <u>www.ArthursTractors.com</u> • 877-254-FORD (3673) • Fax: 724-349-3633 WE ARE NOT RESPONSIBLE FOR MIS-PRINTS OR PRICE CHANGES



REPLACES L609-104 Cylinder packing kit. For H800-5, 55000CR. Hydraulic Cylinder Seal Kits L609-145 Cylinder packing kit. For H800-51, 85, 87, 89, HSK2002 Seal Kit, for 2" bore HTL & HSL Series top and 90, 92, 93, 94, 95, 100. side link cylinders. Contains seals and o-rings for 2" cylinder repair, (Ref. A). For cylinders -REPLACES Hydraulic Hose Assemblies HTL2101, HTL2102, HTL2103, HSL2201, HSL2202, HSL2203, Kit HSK2002 replaces old kit HSK2001. HV4970 Hose, 18". HSK3002 Seal Kit, for 3" bore HTL & HSL Series top and DGPNB950S1-KIT Kit assembly, includes 1-spool valve side link cylinders. Contains seals and o-rings (non-detent/spring centering), hoses, dust cover, for 3" cylinder repair. For cylinders-HTL3101, couplers, handle & valve mounting kit. HTL3101M, HTL3102, HTL3102M, HTL3103, E4NNB968BB Hose, valve to coupler, 1-wire braid. 3/8" I.D. x HTL3103M, HTL3105, HTL3105M, HTL3106, 25", 9/16"-18 ORB male swivel 90à «M, HTL3106M, HSL3201, HSL3201, HSL3201M, 6[degree]à » elbow one end x 3/4"-16 ORB HSL3202, HSL3203, HSL3203M. Kit HSK3002 male solid other end. Use with TISCO B950 replaces old kit HSK3001. valves when using OEM 3/4" ORB female REPLACES coupler half. Cylineder Packing Kits for **Backhoes & Loaders** HV4958 Hose, 46". HV4959 Hose, 48". HV4971 Hose, 21". DGPNB950S2-KIT Kit assembly, includes 2-spool valve 309949 Seal, Packing (non-detent/spring centering), hoses, dust cover, couplers, handle & valve mounting kit. 309940 Seal, Packing HV4972 309946 Seal, Packing HV4961 Hose, Hose Assembly 309939 Seal, Packing 1/4 NPT Male solid 309948 Seal, Packing DGPNB950K1-KIT Kit assembly, includes 1-spool valve (pressure detent), hoses, dust cover, couplers, handle & 309957 Seal, Packing valve mounting kit. HV4962 Hose, Hose Assembly 251165 Seal, Packing 1/4 NPT male solid 309959 Seal, Packing HV4973 REPLACES Cylinder Packing Kits for DGPNB950K2-KIT Kit assembly, includes 2-spool valve (pressure Wagner detent), hoses, dust cover, couplers, handle & valve mounting kit. E1NNB950AB Valve, single-spool, (non-detent/spring centering) less handle. H31-SPL-30 Hose, 30". HV4964 Hose, Hose Assembly 1/4 NPT male solid L609-94 Cylinder packing kit. For H800-31, 32, 39, 45, E1NNB950BB Valve, double-spool, (non-detent/spring 49, 54, 55, 59, 62, 63, 67. centering) less handle.





HV4966	Hose, Hose Assembly 1/4 NPT Male solid	C9NNH891A	Nut for pivot bolt.
H31-SPL-36		721FSO-3/8	
HV4967	Hose, Hose Assembly	HV8510	Bolt, valve mounting, 7/16" -14 x 1-1/4".
	1/4 NPT	7/16-14X3-3/4	
D9NNB950BB	Valve, single-spool, pressure detent, less handle.	HV4908	Bolt, valve mounting, 7/16" -14 x 2-1/2".
292838	Hose, 24" overall length, 3/8" I.D., 1 wire braid, 100 R1-AT, 3/8" NPT male 90à «M,	WH06U-L06	
	6[degree]à » swivel x 3/8" NPT female solid. Fits 730 loader.	REPLACES	Hose Assemblies for Loaders & Backhoes
E2NNB950CA	Valve, double-spool, pressure detent, less handle.		
HV4976	Hose, 39".		()
H31-SPL-26	Hose		
HV4977	Hose, 44".	D8NND558EA	Hose, valve bank to cylinders (6 used). Fits
8250-4	Coupler		backhoes 735, 750, 755.
HV4978	Hose, Hose Assembly 1/4 NPTM solid	292838	Hose, 24" overall length, 3/8" I.D., 1 wire braid, 100 R1-AT, 3/8" NPT male 90à «M, 6[degree]à » swivel x 3/8" NPT female solid.
9006-4	Double break-away clamp.		Fits 730 loader.
HV4979	Hose, Hose Assembly 1/4 NPTM solid	292841	Lift cylinder extension hose, 24" overall length, 3/8" I.D., 1 wire braid 100 R1-AT, 7/8"-14 ORB male swivel x 7/8"-14 37à ūM, 6[degree]à Ż
HV4980	Hose, Hose Assembly		flare male solid. Fits 735 loader.
9507-4-1H	Automatic dust covers.	7701142	Hydraulic hose assembly. For use on 740 series loaders. 24" bucket cylinder hose. Models
D6NND916D	Bracket, hose coupler.		include 19-421, 19-450, and 19-451. 4 hoses used on each model.
HV4981	Hose, Hose Assembly 1/4 NPTM solid	REPLACES	Hose Connector
HV4982	Hose, Hose Assembly		sume
309972F	Handle & valve mounting kit, single-spool.		
309973F	Handle & valve mounting kit, single-spool.		
D3NNB936A	Handle with blue vinyl coated grip, for 1 & 2 spool valves.	CU878FO	for pipe thread hydraulic hose. On 713 & 723 backhoes. Female 1/2" NPT to male special Ford thread and o-ring tube extension.
DHPN485A	O-ring kit, valve mounting.		
C9NND912A	Pivot for hydraulic control valve handle.		
D2NNH889A	Pivot bolt for handles.		
		I	




F-6-221

# REPLACES Hydraulic Coupler Tips & Adaptors



8010-4P	Male tip, poppet style, has a 1/2" NPT thread. Can replace Ford hydraulic tips D7NNB964A, D5NNB964A, D3NNB964A, D3NNJ964A, D1NNB964A, C9NNB964A, C9NNB964B, C7NNB964A. Used on 6X & 6Y series 7000-9000 (1965 & up); 7 Ag & Industrial (1975 & up); 8000, 9000, TW10, TW20, TW30 (1968 & up). Replaces 5090-4.
S25-4-3D	Hydraulic adapter. Adapts John Deere male tip to Ford female coupler.
4065-4L	Long adapter. John Deere to Ford.
D5NNB964A	Male tip-check valve assembly, implement half. Replaces Ford poppet-type assembly & OEM D3NNB964AA, D1NNB964A, C9NNB964B tips; fits tractor series 2000-9000 (1965 & up); D5NNB964A on tractor series 2600-9700 (1975 & up); TW10, TW20, TW30 (1979 & up).
4075-4L	Specially designed long adapter. I.H.C. to Ford.
REPLACES	Hydraulic Coupler Kit
REPLACES HV4298	Hydraulic Coupler Kit Coupler Kit, for 4000 series valves. Contains: 2 quick couplers (S20-4), 2 hoses, 44 (H31-SPL-44), double break- away clamp (S24-4), quick-cover assembly (HV4957).
	Coupler kit, for 4000 series valves. Contains: 2 quick couplers (S20-4), 2 hoses, 44 (H31-SPL-44), double break- away clamp (S24-4),
HV4298	Coupler kit, for 4000 series valves. Contains: 2 quick couplers (S20-4), 2 hoses, 44 (H31-SPL-44), double break- away clamp (S24-4), quick-cover assembly (HV4957).
HV4298 S20-4	Coupler kit, for 4000 series valves. Contains: 2 quick couplers (S20-4), 2 hoses, 44 (H31-SPL-44), double break- away clamp (S24-4), quick-cover assembly (HV4957). Quick coupler, 2 each.







REPLACES

### **Remote Hydraulic Valves and Valve Parts**



These valves and valve parts are for late model Ford tractor applications (Ag and Industrial). The valves bolt directly to tractor top hydraulic cover in place of the accessory plate. Control handles are operated from RH side of operators seat. Tisco kits include valve, handle & mounting kit (handle, pivot bolt & nut, mounting bolts, o-ring & seal kit). Control handle grip is coated with blue heavy durable vinyl which is molded to cast metal handle.

Application: The valves listed below can be used on the following model (Ag & Industrial) tractors: 500 thru 900 (1955 thru 1961); 2000 thru 4000 (USA production thru 1964); 2000 thru 5000 (1965 to 1975); 2600 thru 6600 (1975 to 1981); 2610, 3610, 4610, equipped with single pump hydraulic system, (1981 to -).

Complete Kit	Valve	Handle Kit	Description
E1NNB950AB-KIT	E1NNB950AB	309972F	Kit assembly, includes single spool valve (non-detent/spring
			centering) and handle & valve mounting kit
E1NNB950BB-KIT	E1NNB950BB	309973F	Kit assembly, includes double spool valve (non-detent/spring
			centering) and handle & valve mounting kit
D9NNB950BB-KIT	D9NNB950BB	309972F	Kit assembly, includes single spool valve (pressure detent) and
			handle & valve mounting kit
E2NNB950CA-KIT	E2NNB950CA	309973F	Kit assembly, includes double spool valve (pressure detent) and
			handle & valve mounting kit

**REPLACES** Handle Kits Contents

Replaces	Description	Qty in 309972F	Qty in 309973F
HV4908	BOLT	2	2
7/16-14X3-3/4	CAPSCREW	2	2
HV8510	CAPSCREW	2	2
C9NNH891A	NYLOC SCREW NUT	1	2
DHPN485A	O-RING KIT	1	1
D3NNB936A	VALVE HANDLE	1	2
D2NNH889A	VALVE PIN	1	2





REPLACES

### Remote Hydraulic Valve Kits With Hose & Couplers




For late model Ford tractor applications (Ag and Industrial). These kits include valve, hoses, hose couplers & coupler bracket, self-closing dust covers and handle mounting kit. Valves are of current OEM design and bolt directly to tractor top hydraulic cover in place of accessory plate. Control handles are operated from RH side of operators seat.

Application: These valves can be used on the following model (Ag and Industrial) tractors: 500 thru 900 (1955 thru 1961); 2000 thru 4000 (USA production thru 1964); 2000 thru 5000 (1965 to 1975); 2600 thru 6600 (1975 to 1981); 2610, 3610, 4610, equipped with single pump hydraulic system, (1981 to -).

Complete Kit	Valve	Handle Kit	Description
DGPNB950S1-KIT	E1NNB950AB	309972F	Kit assembly, includes single spool valve (non-detent/spring centering), hoses, dust cover, handle & valve mounting kit
DGPNB950S2-KIT	E1NNB950BB	309973F	Kit assembly, includes double spool valve (non-detent/spring centering), hoses, dust covers, couplers, handdle & valve mounting kit
DGPNB950K1-KIT	D9NNB950BB	309972F	Kit assembly, includes single spool valve (pressure detent), hoses, dust cover, couplers, handle & valve mounting kit
DGPNB950K2-KIT	E2NNB950CA	309973F	Kit assembly, includes double spool valve (pressure detent), hoses, dust covers, couplers, handle & valve mounting kit
REPLACES			

Replaces	Description	Qty in DGPNB950S1-KIT	Qty in DGPNB950S2-KIT	Qty in DGPNB950K1-KIT	Qty in DGPNB950K2-KIT
8250-4	BODY HALF FEMALE	2	4	2	4
D6NND916D	BRACKET HYD	1	1	1	1
9006-4	CLAMP	1	2	1	2
9507-4-1H	DUST COVER	1	2	1	2
H31-SPL-26	HYD HOSE ASSY	2	4	2	4







REPLACES

### **Deluxe Remote Hydraulic Valve Kits**



Built in Mexico, model 5900 was introduced in the USA in May, 1985. In May 1986, the hydraulic lift cover was upgraded to the Series-10 design. Our deluxe Remote Hydraulic Valve Kits will fit the 5900 tractors with the upgraded (Series-10) hydraulic lift cover. Application: Ford 5900 tractors (5-1987 to -).

HV5920 Kit assembly, includes 2-spool valve, valve box with handles.

HV5930 Kit assembly, includes 3-spool valve, valve box with handles.

Replaces	Description	Qty in HV5920	Qty in HV5930
D6NND916D	BRACKET HYD	1	1
9006-4	CLAMP	2	3
9507-4-1H	DUST COVER	2	3
2H10120RF140RM	HCA264 ADAPTOR	1	1
HV4897	HOSE 30 INCH	1	1
HV4898	HOSE 40 INCH	1	1
H31-SPL-30	HYD HOSE ASSY	2	2
H31-SPL-44	HYD HOSE ASSY	2	4
HV4992	VALVE BOX	1	0
HV4993	VALVE BOX	0	1





REPLACES

### Remote Hydraulic Valve Kit for Ford 20-Series Tractors (Japan)



**HV4118** Kit assembly, includes 1-spool valve with handle.

HV4124 Kit assembly, includes 2-spool valve with handles

**HV4125** Kit assembly, includes 2-spool valve, valve box with handles.

Replaces	Description	Qty in	Qty in	Qty in
		HV4118	HV4124	HV4125
5006-4	CLAMP DOUBLE	1	2	2
4250-4	COUPLER	2	4	4
60UB-06X06	HSA12	2	2	2
	ADAPTOR			
60SB-06X06	HSA2 ADAPTOR	1	1	1
HV4945	HYD ADAPTER	1	1	1
	PLATE			
H31-SPL-30	HYD HOSE ASSY	2	4	4
HV4959	HYD HOSE ASSY	3	3	3
HV4020	HYDRAULIC	0	1	0
	VALVE KIT			
HV4940	POWER PLUG	1	1	1
	KIT			
HV4957	QUIK-COVER	1	2	2
HV4984	VALVE BOX	0	0	1

epiacemer	ii pa	arts to
FO	R	D



### REPLACES

### Remote Hydraulic Vavle Kits for Ford Tractors (Japan)

The remote valve kits are complete with hoses, quick-couplers, clamps and Tisco quick-covers. Two versions are being offered; Economy and Deluxe. The Deluxe Kit also includes valve box and H.D. handles. **Application:** Ford Tractor Models 1700, 1900, 1710, 1910 & 2110 (Japan).

fit



control
t

HV4126 Economy kit assembly, includes 2-spool valve with handles. Tractors less Draft control

HV4127 Deluxe kit assembly, includes 2-spool valve, valve box with handles. Tractors less Draft control

HV4117 Economy kit assembly, includes 1-spool valve with handles. Tractors WITH Draft control

HV4128 Economy kit assembly, includes 2-spool valve with handles. Tractors WITH Draft control

HV4129 Deluxe kit assembly, includes 2-spool valve, valve box with handles. Tractors WITH Draft control

Replaces	Description	Qty in					
		HV4116	HV4126	HV4127	HV4117	HV4128	HV4129
HV4950	ADAPT	1	1	1	0	0	0
	PLATE KIT						
5006-4	CLAMP	1	2	2	1	2	2
	DOUBLE						
4250-4	COUPLER	2	4	4	2	4	4
HV4907	HYD	0	0	0	1	1	1
	ADAPTER KIT						
HV4958	HYD HOSE	1	1	1	1	1	1
	ASSY						
HV4959	HYD HOSE	1	1	1	1	1	1
	ASSY						
HV4970	HYD HOSE	1	2	2	1	2	2
	ASSY						
HV4971	HYD HOSE	1	2	2	1	2	2
	ASSY						
HV4957	QUIK-COVER	1	2	2	1	2	2
HV4984	VALVE BOX	0	0	1	0	0	1





### REPLACES

### HV4000 Series Remote Hydraulic Valve Kits

Application: Ford Tractor Models 500 thru 6600, U.K. & U.S.A., with single pump hydraulic system (1955 thru 1981).




- HV4111 Kit assembly, includes 1-spool valve with handle.
- HV4120 Kit assembly, includes 2-spool valve with handle.

HV4121 Kit assembly, includes 2-spool valve with handle (has float on one spool).

HV4122 Kit assembly, includes 2-spool valve, valve box with handles.

Replaces	Description	Qty in HV4111	Qty in	Qty in HV4121	Qty in HV4122
S42-4	CLAMP	1	2	2	0
5006-4	CLAMP	0	0	0	2
0000 4	DOUBLE	Ũ	Ũ	Ũ	-
4250-4	COUPLER	0	0	0	4
S40-4	COUPLER	2	4	4	0
60SB-06X06	HSA2	2	2	2	0
	ADAPTOR				
H31-2M-12	HYD HOSE	2	2	2	0
	ASSY				
HV4970	HYD HOSE	1	2	2	2
	ASSY				
HV4971	HYD HOSE	1	2	2	2
	ASSY				
HV4976	HYD HOSE	0	0	0	1
	ASSY				
HV4977	HYD HOSE	0	0	0	1
	ASSY				
292838	LBP HOSE	2	2	2	0
	ASSY				
HV4957	QUIK-COVER	1	2	2	2
HV4992	VALVE BOX	0	0	0	1
HV4902	VALVE	1	1	1	1
	PLATE KIT				







F-6-228

REPLACES

Hydraulic Cylinder Kits For Ford 20 Series Application: Ford tractor models: 1320 (10-1987 to -), 1520 (10-1987 to -), 1720 (10-1987 to -), 1920, 2120, (Japan).



HCKF292 2-spool valve and cylinder kit complete.

HCKF293 3-spool valve and cylinder kit complete.

Replaces	Description	Qty in	Qty in
		HCKF292	HCKF293
60UB-06X06	HSA12 ADAPTOR	2	2
60SB-06X06	HSA2 ADAPTOR	1	1
HV4945	HYD ADAPTER PLATE	1	1
HV4959	HYD HOSE ASSY	3	3
HV4961	HYD HOSE ASSY	2	2
HV4962	HYD HOSE ASSY	1	3
HV4964	HYD HOSE ASSY	1	1
HSL2203	HYD SIDE LINK	1	1
HTL2102	HYD TOP LINK	1	1
HV4940	POWER PLUG KIT	1	1
HV4984	VALVE BOX	1	0
HV4985	VALVE BOX	0	1
HV4023	VALVE LESS HANDLE	1	0
HV4033	VALVE LESS HANDLE	0	1



F-6-22

Replacement parts to fit





Application: Ford Tractor Models 1700, 1900, 1710, 1910 & 2110 (Japan).





- HCKF192D Draft control equipped tractors, 2-spool valve kit complete.
- HCKF193D Draft control equipped tractors, 3-spool valve kit complete.
- HCKF192R Regular (no draft control), 2-spool kit complete.
- HCKF193R Regular (no draft control), 3-spool kit complete.

Replaces	Description	Qty in HCKF192D	Qty in HCKF193D	Qty in HCKF192R	Qty in HCKF193R
HV4950	ADAPT	0	0	1	1
	PLATE KIT				
HV4907	HYD	1	1	0	0
	ADAPTER				
	KIT				
HV4958	HYD HOSE	1	1	1	1
	ASSY				
HV4959	HYD HOSE	1	1	1	1
	ASSY				
HV4961	HYD HOSE	2	2	2	2
	ASSY				
HV4962	HYD HOSE	1	1	1	1
	ASSY				
HV4964	HYD HOSE	1	1	1	1
	ASSY				
HV4966	HYD HOSE	0	1	0	1
	ASSY	_	_	_	
HV4967	HYD HOSE	0	1	0	1
	ASSY	-			
HSL2203	HYD SIDE	1	1	1	1
HTL2102	HYD TOP	1	1	1	1
			0		0
HV4984	VALVE BOX	1	0	1	0
HV4985	VALVE BOX	0	1	0	1
HV4023	VALVE	1	0	1	0
	LESS				
111/4022		0	1	0	1
HV4033	VALVE	U	Т	U	Т
	HANDLE				





### **REPLACES** Hydraulic Cylinder Kits

**Application:** Ford Tractor Models 500-900 (55-60); 2000-4000 (USA-1964), 2000-5000 (65-75); 2600-6600 (75-81), Industrials 230-545. With single pump hydraulic system.

Not for Ag 10-Series or Industrial C or D-Series tractors



HCKF262 2-spool valve and cylinder kit complete.

HCKF263

3-spool valve and cylinder kit complete.

Replaces	Description	Qty in	Qty in
		HCKF262	HCKF263
HV4976	HYD HOSE ASSY	1	0
HV4977	HYD HOSE ASSY	1	1
HV4978	HYD HOSE ASSY	2	2
HV4979	HYD HOSE ASSY	1	1
HV4980	HYD HOSE ASSY	1	1
HV4981	HYD HOSE ASSY	0	1
HV4982	HYD HOSE ASSY	0	1
HSL3201	HYD SIDE LINK	1	1
HTL3101	HYD TOP LINK	1	1
HV4992	VALVE BOX	1	0
HV4993	VALVE BOX	0	1
HV4023	VALVE LESS HANDLE	1	0
HV4033	VALVE LESS HANDLE	0	1
HV4902	VALVE PLATE KIT	1	1



-			
Pon	lacement	narte	to tit
NED	lacement	parts	ισπι



REPLACES	Hydraulic Adapter Kit	REPLACES	Valve Box & Handle Kits
HV5902	Adapter kit. Can replace OEM adapter plate 9613790. Adapter plate in HV5902 kit features three ports: (1) pressure port, (1) power-beyond port and (1) return port. All ports 3/4" - 16 ORB. Kit contains adapter plate, o-rings, mounting bolts, plugs, and instructions. For models with single-pump hydraulic system, tractors 500-900 (1955-1960); 2000, 4000 (USA-1964); 2000-5000 (1965-1975); 2600-6600 (1975-1981); industrials 230-545. Not for AG 10 series, 5900 produced after April 1986, or industrial C- or D- series tractors.	HV4992 HV4984	<ul> <li>Valve box. Two-handle assembly, vertical mount. Constructed as HV4984 and HV4985. Handles are designed to allow easy, comfortable operation of all valve spools. Designed to mount on vertical fender surface to the right of operator's seat. Installed and field tested on 35 hp and up Ford utility tractors. Will accomodate HV4023 valve (or equivalent size valve).</li> <li>Valve box assembly with handles installed, top mount. 2 handles, all steel (14-gauge). Unit has built-in handle pivots complete with actuator links and two 3/8"</li> </ul>
HV4902	Adapter plate kit. Contains 1-HV4901 adapter plate, mounting cap screws, o-rings and mounting instructions. For tractors with single-pump hydraulic system 500-900 (1955-1960); 2000-4000 (USA-1964); 2000-5000	6	dia. steel handles; one straight and one offset. With durable plastic knobs. Removeable cover with edge protectors for operator protection. Will accomodate HV4023 valve (or equivalent size valve). Designed to mount on top of flat top fenders.
HV4907	(1965-1975); 2600-6600 (1975-1981); industrials 230-545. Adapter plate kit, tractors with draft control on 3-pt. hitch. This is a 2-port adapter P-pressure and	HV4985	Valve box with 3 handles installed. One straight handle in center position flanked by two offset handles. Will accomodate HV4033 valve (or equivalent size valve).
	R-Return. Ports are 9/16"-18 ORB thread. Kit contains o-ring seals, 1-60UB 06X06 90Ë swivel fitting, metric hardware, and mounting instructions. For Ford (Japanese) 1710, 1910, and 2110 tractors.	HV4993	Valve box. Three-handle assembly, vertical mount. Will accomodate HV4033 valve (or equivalent size valve).
HV4950	Adapter plate kit, tractors without draft control on 3-pt. hitch. Kit contains adapter, o-ring seals, metric bardware, and mounting	HV4910	Kits Handle kit. Includes handle & mounting kit with hardware. For
	metric hardware, and mounting instructions. This is a 2-port adapter. All ports are 9/16-18 ORB thread. For Ford (Japanese)	N	all standard HV4000 Series valves.
	1710, 1910, and 2110 tractors.	HV4911	Handle Mounting Kit. Includes bail & hardware for mounting the HV4910 standard handle.





			HIDRAULICS
HV4917	Handle Kit, same as HV4910 except has special bracket used for 90° rotated handle. Replaces HV4912.	HV4941	Closed Center Plug Kit. Can be installed in HV4000 valve in place of Allen Head Plug in side of valve casting. Allows use of valve with closed center hydraulic system
HV4916	90° Handle Mounting Kit, includes bracket and hardware for mounting the HV4917 90° handle kit. Replaces HV4913.	6	(such as late John Deere with variable displacement hydraulic pump).
HV4923	Spool Seal Kit. Front & rear spool sealing o'ring For use with full range of HV4000 valves.	gs. HV4023	Hydraulic Valves Valve, 2-spool, 2000 psi. Relief, tandem (4-way)
HV4930	Float Spool Detent Kit. Contains all parts needed to convert standard spool to float spool. An exclusive feature of the HV4000	HV4033	spool, spring center to neutral, less handles. Valve, 3-spool, 2000 psi. Relief, tandem (4 way) spool, spring center to neutral, less handles.
	Series Valves-you can convert a tandem action (4-way) spool to float detent merely by installing the HV4930 kit. Other valve manufacturers require a special valve body or spool for float operation - this cannot be field installed. The HV4000 can be converted in the field. One important exclusion, on any two spool valve, only one spool can be equipped with a float detent.	REPLACES	Replacement Handles and Parts
HV4931	Standard Spring Center Kit. Standard equipment on any valve equipped with spring centering spool control. Kit contains all parts needed to repair or convert	HV4988 HV4989	Handle, offset. Used in HV4984 & HV4895. (Ref. 1) Handle, straight. Used in HV4984 & HV 4895. (Ref. 2)
	existing spool.	HV4990	Handle, short angled. Used in HV4992 & HV4993. (Ref. 3)
HV4932	Three Position Detent Kit (no spring). Any tandem action spool can be converted to detent using	HV4998	Handle, medium angled. Used in HV4992 & HV4993. (Ref. 4)
	this kit. Spool will remain in detented position until physically moved to neutral. Not a pressure	HV4999	Handle, long angled. Used in HV4992 & HV4993. (Ref. 5)
HV4940	release detent kit. Power beyond plug kit. Can be	HV4987	Knob. Used with handles HV4988, HV4989, HV4990, HV4999. (Ref.6)
	installed in HV4000 valve in place of allen head plug in side of valve casting. Allows plumbing additional hydraulic control valve into system.	HV4975	Link Kit, valve handle actuator. Used with handles HV4988-HV4999. (Ref. 7)

		lacement parts	
HITCH AND HYDRAULICS		FORD	
REPLACES	One Spool Valves	REPLACES	Popular O Ring Seals
		NAA533A	O-ring for hydraulic lift piston. For tractor NAA.
HV4010	Valve with handle, single-spool, 2000 psi. Relief, tandem (4-way) spool, spring center to neutral. For small to medium sized tractors, domestic	13-OR	O-ring for hydraulic pump relief plug. 11/16" ID x 7/8" OD.
	and imports.	7A-OR	O-ring for pressure line plug. 3/8" ID x 1/2" OD.
HV4012	Valve, hydraulic, with handle, single-spool multi-valve. No relief, tandem (4-way) spool, convertible to 3-way, spring center to neutral, with 90° rotated handle. For small to medium sized tractors, domestic and imports.	212-OR	O-ring, plate assembly to lift cover. 1-1/8" ID x 1-1/4" OD.
		361-OR	O-ring, plate assembly to lift cover. 1-3/4" ID x 1-7/8" OD.
REPLACES	Two Spool Valves	356-OR	O-ring, hydraulic pump body (vane type pump). 2-1/2" ID x 2-5/8" OD.
		11-OR	O-ring, power steering return line union. Replaces LA33604A. 9/16" ID x 3/4" OD.
		87004S94	1/4" I.D. 1/16" thick.
		87006S94	Plate assembly to lift cover.
HV4020	Valve with handles, two-spool, 2000 psi. Relief, tandem (4-way) spool, spring center to neutral. For small to medium sized tractors, domestic and imports.	87010S94	Lift cylinder to lift cover, hydraulic pump relief valve body.
		87012S94	Plate assembly to lift cover.
HV4021	Valve with handles, two-spool, 2000 psi. Relief, one-spool tandem (4-way) float position with spring center to neutral and one spool tandem (4-way) spring center to neutral. For small to medium sized tractors, domestic and imports.	87020S94	O-ring, fuel valve body. For gas tractors 501, 600, 601, 700, 701, 2000 (1955-1964); 800, 801, 900, 901, to S/N 126524 with 1/4" fuel line (1955-1960). For diesel tractors 501, 601, 701, 801, 901, 2000, 4000 (1958-1964).
REPLACES	Three Spool Valves	8-OR	O-ring, check valve plug. 3/8" ID x 9/16" OD.
	<b>Niee Spool valves</b>	87033S94	Inlet tube and exhaust tube.
		87034S94	Plate assembly to lift cover.
		87035S94	Pressure tube to center housing.
HV4030	Valve with handles, three-spool, 2000 p.s.i. Relief, all spools tandem (4-way) spring center	87036S94	11/16" I.D. 3/32" thick.
	to neutral. For small to medium sized tractors, domestic and imports.	87051S94	O-ring, intake tube to valve pump. For 4-speed transmission models.
		1	

Pump flow control valve.

87053S94





					THE NO LIGO	
87055S94	O-ring intake tube to manifold sidemount. For tractors 8N 1950 & up, side mount.		Replaces 9-OR	Description	Qty in ORD382	
25-OR	O-ring, 1-3/8" ID x 1-5/8" OD.	O-ring 1-3/8" ID x 1-5/8" OD		O-RING 13		
106-OR	O-ring, 2-1/4" ID x 2-1/2" OD.		REPLACES	Hydraulic Top Link Cylinders		
	, , , , , , , , , , , , , , , , , , ,			. 00-0-0-00.		
109-OR	-	O-ring, 2-5/8" ID x 2-7/8" OD.		·		
114-OR	O-ring, 3-1/4" ID x 3-1/2" OD.		HTL2102	Hydraulic top link cylinder, 2" bore.		
115-OR	O-ring, PTO shaft bearing retainer. 3-3/8" ID x 3-5/8" OD.		HTL3101 HTL3103	Top link cylinder. 3" bore.		
121-OR	O-ring, steering gear side cover. 4-1/8" ID x 4-3/8" OD.					
	4-3/0 OD.		REPLACES	Hydraulic Side Link Cylinders		
87111S95	O-ring hydraulic lift piston. For tractors 2000, 3000 (1965-1975); 2600, 3600 (1975-1981); 2610, 3610 (1981-). Replaces NCA533A.					
REPLACES	O-Ring Kit and Display Merchandiser		HSL2201	Hydraulic side link cylinder, 2" bore.		
			HSL2203	Side link cylinder, 2".		
ORD382	O-ring kit and display merchand		HSL3201	Side link cylinder.		
Replaces	Description	Qty in ORD382	REPLACES	A		
1-OR	O-RING	20	REPLACES	Accessory Items	5	
10-OR	O-RING	13	HV4957	Quick-cover assembly. Fo	r	
11-OR	O-RING	13	1104757	Safeway (S42-4) and Pion		
12-OR	O-RING	13	1	double breakaway clamp		
13-OR	O-RING	13		assemblies.	5.00	
14-OR	O-RING	13				
15-OR	O-RING	10	S42-4	Double break-away clamp		
16-OR	O-RING	10		use with S20-4 and S40-4		
17-OR	O-RING	10	4	couplers. Quik-cover asse	embly	
18-OR 19-OR	O-RING	10		HV4957 fits this clamp.	- P	
2-OR	O-RING O-RING	10 20				
20-OR	O-RING O-RING	10	REPLACES	S.O.S. Pipe Dop	е	
21-OR	O-RING	10				
22-OR	O-RING	10	PDT300	Roll, in self-dispenser, 1/2"	tape, 300 inches long.	
23-OR	O-RING	10	-			
24-OR	O-RING	10				
25-OR	O-RING	10	]			
26-OR	O-RING	10				
27-OR	O-RING	10				
28-OR	O-RING	7	4			
29-OR 3-OR	O-RING O-RING	7 20				
30-OR	O-RING O-RING	20 7				
4-OR	O-RING	20	1			
5-OR	O-RING	20				
6-OR	O-RING	20				
7-OR	O-RING	20	1			
8-OR	O-RING	13				

Arthur's Tractors ~ <u>www.ArthursTractors.com</u> • 877-254-FORD (3673) • Fax: 724-349-3633 WE ARE NOT RESPONSIBLE FOR MIS-PRINTS OR PRICE CHANGES



# FORD



192152	Pulley supplied with four rubber bushings for hub with 11/32" pins when used with front mounted loader.
192160	Pulley has four 1/4"-20 threaded holes for hub

when used with front mounted loader.

Arthur's Tractors ~ <u>www.ArthursTractors.com</u> • 877-254-FORD (3673) • Fax: 724-349-3633 WE ARE NOT RESPONSIBLE FOR MIS-PRINTS OR PRICE CHANGES